

SDMS DocID

248163

Superfluid Records Center Z. 1 SITE: Accords Ex Exist: 2.1

## Document Control Number: ACE-J23-35BG0107-P4-0001

II JACOBS

Client, Project and Location				Delive				rder/Task Order 0 0001	
USACE New Bedford Resident Office				Project Note				Project No.	
Ne	w Bedford Ha	arbor Superfund Site		•			351	3G0107	
New Bedford, Massachusetts USACE Contract Number DACW33-03-D-0006				Note No.		.: 079			
Confirmation of				Date Held	02/08/06				
	Project note-	P1		Location	Various				
$\boxtimes$	Client Meetin	ig-P4		Date Issued	02/08/06				
	Other			Recorded By	Mike Anderson				
Subject				Issued By	Mike Anderson				
New	Bedford Har	bor – Client Update I	leeting	the	eld.	alel	_		
				Jacobs Project Manager					
Part	cipants (* Der	notes Part Time Partici							
Client		EPA	Jacobs/SES - NB Boston				Others	16	
Gary Morin		Dave Peterson	Mike Anderson				Steve Wolf		
Mark Anderson		Dave Dickerson	Carl W	Carl Wilson			Paul Dragos		
		Cindy Catri					Don Boye		
		Jim Brown			-				
Ite	m		Ren	narks				Action	
110		Tomaro						Required	

 The Aerovox building has deteriorated in the past year. There is standing water in certain locations, flooring is buckling, and mold growth is progressing.